

कार्यालय कार्यपालन अभियन्ता
लोक निर्माण विभाग (भ/स) संभाग बेमेतरा जिला बेमेतरा (छ.ग.)

जय स्तंभ चौक बेमेतरा

दूरभाष क्र. 07824-222019, फ़ैक्स क्र. 07824-222018

Email:- ee.bemetara@gov.in

ज्ञाप. क्रमांक 5364

/ शिल्प / 23 /

बेमेतरा, दिनांक 24/09/2023

PROFORMA FOR THE SAFETY OF SCHOOL BUILDING PART -1

(to be filled by the Head of School/Institute)

1. Name of the school : D.A.V. MUKHYAMANTRI
PUBLIC SCHOOL, JANTA
2. Location : Village – Janta, Post – Odiya,
Dist – Bemetara (C.G.)
3. Plot Area :
4. Plinth Area :
5. Number of Storey's : 01
6. Year of Construction of Building : 2021
7. **If the building has constructed under the Supervision of the qualified Engineer,
the following Details may be given**
 - a. Name of the Engineer with qualification :
 - b. Address of Engineer :
 - c. Set of Structural drawings used in the construction,
if available
 - d. Name & address of Architect with qualification :
8. **Whether the building has been constructed for the purpose**
 - a. School : YES
 - b. Residential Purpose and converted for use as a School: NO
9. **Materials used for roofs**
 - a. R.C.C. Slabs/R.B.C. Slabs : YES
 - b. R.S. Joist & Battons :
 - c. Wooden Joist & Battons :
10. **Material used for walls**
 - a. Mud Mortar :
 - b. Cement Mortar : YES
 - c. Lime Mortar :
11. **Floorin**
 - a. Conglomerate : YES
 - b. Terrazo :
 - c. Brick Paving :
12. **A detailed drawing indicating dimensions of the rooms
Alongwidth size and location of doors and windows (attached)**

कार्यालय कार्यपालन अभियन्ता
लोक निर्माण विभाग (भ/स) संभाग बेमेतरा जिला बेमेतरा (छ.ग.)
जय स्तंभ चौक बेमेतरा
दूरभाष क्र. 07824-222019, फ़ैक्स क्र. 07824-222018
Email:- ee.bemetara@gov.in

ज्ञाप. क्रमांक 5365

/ शिल्प / 23 /


बेमेतरा, दिनांक 24/08/2023


PART-II

(To be filled by the S.D.E.)

- a) I have visited the above mentioned school on dated – **18-08-2023** And have visually inspected it from all angles of safety and find it fit for normal use as School building.
- b) In case any addition / alteration or expansion and modification to his building is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/foundations or sagging of roofd etc. Immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use upto (indicate upto which it can be used) 17-08-2024


Sub-Engineer


Sub Divisional Officer
PWD (B&R) Sub Division
Nawagarh


Executive Engineer
PWD (B&R) Division
Bemetara